

Table 1. Field Activity Log, 2Q 2006	
Date	Activity
4/4/06	Replace brushes and install motors in all high volume air samplers
4/5/06	Cancel Event 73 due to quarterly maintenance; begin calibration all high volume air samplers
4/7/06	Complete calibration of all high volume air samplers
4/11/06	Conduct Event 74 (13 of 13 PM ₁₀ /TSP samples completed)
4/17/06	Conduct Event 75 (12 of 13 PM ₁₀ /TSP samples completed; Dickson chart omitted at AM-1-TSP)
4/23/06	Conduct Event 76 (13 of 13 PM ₁₀ /TSP samples completed)
4/26/06	Clean and re-grease shim plates on all PM ₁₀ high volume air samplers
4/29/06	Conduct Event 77 (13 of 13 PM ₁₀ /TSP samples completed)
5/5/06	Conduct Event 78 (13 of 13 PM ₁₀ /TSP samples completed)
5/11/06	Conduct Event 79 (13 of 13 PM ₁₀ /TSP samples completed)
5/15/06	Replace pens on all Dickson chart recorders
5/17/06	Conduct Event 80 (12 of 13 PM ₁₀ /TSP samples completed; timer malfunction at AM-4-PM10 high volume air sampler)
5/23/06	Conduct Event 81 (11 of 13 PM ₁₀ /TSP samples completed; timer malfunction at AM-3-TSP and AM-4-TSP high volume air samplers)
5/29/06	Conduct Event 82 (13 of 13 PM ₁₀ /TSP samples completed)
5/31/06	Clean and re-grease shim plates on all PM ₁₀ high volume air samplers
6/4/06	Conduct Event 83 (13 of 13 PM ₁₀ /TSP samples completed)
6/10/06	Conduct Event 84 (13 of 13 PM ₁₀ /TSP samples completed)
6/12/06	Replace brushes and install motors in all high volume air samplers
6/13/06	Begin calibration of all high volume air samplers
6/14/06	Complete calibration of all high volume air samplers
6/16/06	Conduct Event 85 (13 of 13 PM ₁₀ /TSP samples completed)
6/22/06	Conduct Event 86 (13 of 13 PM ₁₀ /TSP samples completed)
6/28/06	Conduct Event 87 (13 of 13 PM ₁₀ /TSP samples completed)